



EXPLANATION

- Line showing approximate decline of water levels in the Carrizo aquifer, 1970-1990
Interval is 20 feet
- Outcrop of the Carrizo Sand
- Contact
Dotted where concealed or approximately located
- Fault, dashed where approximately located
D, downthrown side; U, upthrown side
Only those faults in the outcrop are shown
- Approximate downdip limit of fresh to slightly saline water (less than 3,000 milligrams per liter dissolved solids) in the Carrizo aquifer

Figure 22
Projected Decline of Water Levels
in the Carrizo Aquifer, 1970-1990

Base compiled from Army Map Service Maps, Corp of Engineers, U.S. Army, Washington D.C.